



2032 ADS PCM Error Correction

January 18, 2023

Tyler Butikofer
Senior Engineer

Fixes

- Assign the correct shapes to seven wind units
- Added VOM to eight batteries
- Updated two small cogens from hourly resource to thermal with generic heat rates, VOM, etc.
- Generic Solano wind units assigned shape from existing wind since low-capacity factor with other unit-specific shapes
 - When applying the changes in V2.3.2 GridView, created duplicates in the hourly general table and had a duplicate shape ID for two shapes
- Update the thermal general table with correct max capacity



Contact:

Tyler Butikofer

tbutikofer@wecc.org